Palam Drain and Eastern approach (Maude Road) is already under DDA's consideration. Approach from Najafgarh Road has already been provided. The approach from NH-8 through Southern boundary of Airport has recently been approved and the work is about to begin.

Metero-rail:—A detailed Project Report was submitted by the Delhi Metro Rail Corporation for the Barakhamba Road-Cannaught Place-Dwarka Corridor, recently and it is being scrutinised.

(e) The city is likely to be fully developed in about 5—10 years depending upon the timely availability of basic amenities from DVB, DJB, Govt, of NCT of Delhi and all other participating agencies and also the allottees.

Distemper in Government Quarters

†454. SHRI ANIL SHARMA: Will the Minister of URBAN DEVELOPMENT AND POVERTY ALLEVIATION be pleased to state:

(a) whether it is a fact that quarters of some of Government's residential areas are whitewashed with distemper while in some other areas they are just whitewashed with lime stone;

(b) if so, the details thereof;

(c) the instructions of Government in this regard;

(d) the scheme under Government's consideration for improvement in quality of whitewash;

(e) whether Government propose to issue orders for whitewashing all the quarters with distemper; and

(f) if so, by when?

THE MINISTER OF STATE IN THE MINISTRY OF URBAN DEVELOPMENT AND POVERTY ALLEVIATION (SHRI BANDARU DATTATRAYA): (a) Yes Sir. It is true that in some Govt, residential area, distemper is used while others are white washed with lime.

(b) In all newly constructed quarters of type-I, II & HI, distemper is done in all the rooms and white wash is done on the ceiling and in kitchen & toilet. In all servant quarters also white wash is done. In newly constructed

†Original notice of the question was received in Hindi.

type-IV quarters, distemper is used in the drawing room and dining room and in other areas white wash is done. In new type-V houses, distemper is done in the bedrooms, study room, drawing room and dining room while white wash is done in the remaining portions.

In all old houses from type I to IV and in all servant quarters, only white wash using lime is done. In all old type V quarters distemper is done in bedroom, study room, drawing room, dining room and white wash is done in the rest of areas.

(c) The directives of Government, in this regard are given in CPWD Plinth Area Rate 1976 which were subsequently revised in 1992.

(d) Detailed instruction regarding the quality and specifications to be followed for white wash is given in CPWD Specification 1996 Vol. 1 to 6. AH CPWD field units are expected to follow these instructions. In case any complaints is received regarding inferior quality of white wash immediate action is taken to redress the complaint. The Quality Control Wing of CPWD also carries out inspections from time to time to ensure proper quality in works.

In all new constructions distemper/white wash is done as per provision in CPWD Plinth Area Rates of 1992. After comming into force of new sepcifications in 1992 distemper is being used in some areas in old quarters also depending upon availability of funds etc.

(e) No, Sir. There is no proposal under consideration to change white wash into distemper in all the quarters.

(f) Does not arise in view of reply at (e) above.

Parking Space for Residents of Dwarka

455. SHRI ANIL SHARMA: Will the Minister of URBAN DEVELOPMENT AND POVERTY ALLEVIATION be pleased to state:

(a) whether it is a fact that DDA has not made any provision for parking space for the residents of DDA flats, pocket-13, (manglapur) Dwarka, New Delhi;

(b) whether it is also a fact that the terrace of these flats are without side walls and iron staircase making the terrace dangerous and accident-prone;

(c) if so, whether Government propose to make arrangements for parking space and also construct proper Concrete staircase and side walls on the terrace of the flats to make it safe and secure; and

(d) if so, the details thereof and if not, the reasons therefor?